

**BASIC IMAGERY  
INTERPRETATION  
REPORT**

Reviewed by NGA.

**CHIN-CHI BARRACKS AREA SW**



25X1

**GROUND FORCE FACILITIES**


**CHINA**

**JULY 1971**

25X1



**TOP SECRET** 25X1



**RCA-07/0067/72**

**COPY NO 100**

**10 PAGES**



25X1

TOP SECRET

07/0067/72

25X1

25X1

INSTALLATION NAME AND MILITARY REGION

COUNTRY

Chin-chi Barracks Area SW (Lan-chou MR)

CH

UTM COORDINATES

GEOGRAPHIC COORDINATES

25X1

NA

37-53-45N 106-01-00E

MAP REFERENCE

USATC. Series 200, Sheet 0383-13, scale 1:200,000

LATEST IMAGERY USED

NEGATION DATE

25X1

NA

## REFERENCE DATA

25X1

### DOCUMENTS:

25X1

1. CIA [ ] IMAGERY ANALYSIS REPORT,  
DDI/IAR 9302, JUN 69 (TOP SECRET [ ])

25X1

### REQUIREMENT:

Departmental Requirement Cite: CIA-C-SRO 86, 362

COMIREX Basic Requirement Cite: BF G-04

NPIC/IEG/EGD/NKB Project 222995CI

### COLLATERAL:

NOTE: This report is published as an interim Basic Report with the concurrence of DIA.

TOP SECRET

25X1

25X1

TOP SECRET

25X1

25X1

INSTALLATION: Chin-chi Barracks Area SW, Lan-chou MR, China

LOCATION: Chin-chi Barracks Area SW is in the center of Ching-tung-hsia, which is 6.2 nautical miles southwest of Chin-chi.

GENERAL: This small wall-secured installation is in a small city which is comprised primarily of construction camps or communes associated with a hydroelectric dam project situated on the southwest corner of the city, on the Huang Ho (river).

The barracks area, first photographed on [REDACTED] [REDACTED] has undergone small expansion projects periodically since then, and was undergoing construction when last seen on [REDACTED]

25X1

The generally informal configuration of this installation and the vehicular activity observed indicate a small military engineer installation probably involved with the hydroelectric construction activity in the area.

Accuracy Statement: [REDACTED] Conversion from square meters to square feet was determined by the factor: 1 square meter equals 10.76 square feet.

25X1

The number in parentheses after vehicle storage building dimensions (e.g. 7-10w) indicates the estimated building capacity for wheeled vehicles based on a CIA/IAS study.<sup>1</sup>

Function/Description

Area Aa Billeting Area

4 barracks #13-16  
4 barracks #18-21  
4 barracks #23,24,26,27  
3 barracks #5-7  
1 barracks #1  
1 barracks #2  
1 barracks #4  
1 messhall #3  
2 admin/support bldgs #10,11  
3 utility sheds #22,25,28  
1 basketball court #9  
2 minor support bldgs #8,17  
1 latrine #12

Floorspace of Major Buildings - Area Aa Barracks

Area Ab - Billeting Area

3 barracks #36,41,42  
1 barracks #37  
2 barracks #46,55  
2 barracks #47,56  
2 barracks #48,49  
1 barracks #50  
4 barracks #51,52,58,59  
2 barracks #53,54  
1 admin bldg #44  
1 auditorium/messhall #45  
2 support bldgs #35,60  
1 gate house #43  
1 latrine #61  
1 minor support bldg #57 without roof  
1 stock pen #38  
2 basketball courts #39,40

25X1

25X1

25X1

25X1

TOP SECRET

25X1

25X1

25X1

Function/Description	Overall Dimensions		Floorspace	
	Meters	Feet	Sq Meters	Sq Feet

Floorspace of Major Buildings - Area Ab  
Barracks

25X1

Area Ba - Vehicle Storage/Maintenance Area

1 vehicle storage/maintenance  
bldg #31 (5-7w)  
1 vehicle storage/maintenance  
bldg #32 (6-9w)  
1 vehicle storage/maintenance  
bldg #34 (8-11w)  
2 admin/support bldgs #30,33  
1 minor support bldg #29  
without roof

25X1

Floorspace of Major Buildings - Area Ba

Vehicle Storage/Maintenance (19-27w)

25X1

Floorspace of Major Buildings -

Barracks

Vehicle Storage/Maintenance (19-27w)

25X1

Chronological Listing of Facilities, Vehicles and Equipment,\* and Activity

Base Data

25X1

Floorspace of Major Buildings

25X1

Area Aa - Barracks

Area Ab - Barracks

Area Ba - Vehicle Storage/Maintenance (6-9w)

Installation

Barracks

Vehicle Storage/Maintenance (6-9w)

COMMENTS: Changes which have occurred within the installation from (date of base coverage) to (date of latest coverage) are listed as follows:

25X1

25X1

Area Aa - Billeting Area

2 barracks #1,2 had been added  
2 minor support bldgs #8,17 had been added  
1 latrine #12 had been added.

25X1

Area Ab - Billeting Area

9 barracks #36,41,42,46,47  
50,51,54,56, had been added.  
1 barracks #53 had been extended.

An admin bldg #44, a new auditorium/messhall #45,  
and a support bldg #35 had been added. A long  
construction utility shed/barn had been removed.

Area Ba - Vehicle Storage/Maintenance Area

2 vehicle storage/maintenance bldgs  
#31,34 had been added. (13-18w)

25X1

25X1

25X1

25X1

These changes are reflected in the following chronology:

25X1

Facilities

Base Data established on this mission.

Vehicles and Equipment

Small scale precluded identification.

Activity

None was observed.

Facilities

Area Aa

One minor support bldg #17 and one latrine #12 had been added.

Area Ab

One barracks #51 had been added.

Facilities

No changes were observed.

Vehicles and Equipment

Small scale precluded identification.

Activity

None was observed.

25X1

Area Ba

One vehicle storage/maintenance bldg #31 had been added.

25X1

Vehicles and Equipment

Small scale precluded identification.

Activity

None was observed.

Floorspace of Major Buildings

25X1

Area Aa

Barracks

25X1

Area Ab

Barracks

25X1

Area Ba

Vehicle storage/maintenance

25X1

25X1

Installations

Barracks

25X1

Vehicle storage/maintenance

25X1

25X1

25X1

25X1

Approved For Release 2004/02/23 : CIA-RDP78T04563A001100020001-0

Approved For Release 2004/02/23 : CIA-RDP78T04563A001100020001-0

25X1

TOP SECRET

RCA-07/0067/72

25X1

25X1

25X1

Floorspace of Major  
Buildings

25X1

Facilities

Area Aa

2 barracks #1,2 had been  
added (sq ft)

Barracks

25X1

25X1

Area Ab

Area Ab

3 barracks #36,41,46 had been  
added.

Barracks

25X1

25X1

Half of barracks #54 had been  
added.

(sq ft)

Area Ba

25X1

Barracks #53 had been

Vehicle storage/main-  
tenance

25X1

25X1

25X1

extended (sq ft)

Support bldgs #35 had been  
added.

Installation

Area Ba

Barracks

25X1

Vehicle storage/main-  
tenance bldg #34 had  
been added.

Vehicle storage/main-  
tenance

25X1

25X1

25X1

25X1

Vehicles and Equipment

Area Ba

Approximately six vehicles/  
pieces of equipment were  
observed throughout the  
area. (b)

Activity

Area Aa

A large sign board or  
bulletin board had been  
erected in the courtyard.

Area Ab

A monument was erected at the  
north end of the main access  
road into the area. Agricul-  
tural activity was evident on  
the southwest side of the area.

Area Ba

Support bldg #29 was roofed and  
appeared to be in use.

25X1

TOP SECRET

25X1



Next 3 Page(s) In Document Exempt

**TOP SECRET**

**TOP SECRET**